

Work Order ID 156458

Friday, January 27, 2017 1:22:35 PM

156458

Page 1

Item ID: D4002-041 Accept ***N900040100*** Setup Start ***NS1***
Revision ID: Stop ***NS2***
Item Name: Aux Tank Drain Hose Assy, Fwd
Start Date: 2/1/2017 Start Qty: 4.00 ***4*** Cust Item ID:
Required Date: 2/9/2017 Req'd Qty: 4.00 ***4*** Customer:
Reference:

Approvals: Process Plan: DAS 21 9-89 Date: FEB 02 2017 Tooling: _____ Date: _____ Run Start ***NR1***
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D4002	D								
100		0.00							DAS 13 9-89
100									
Purchasing	Memo	0.00							
Purchasing	Issue P/O: <u>35229</u>								
	Purchase part as per Dwg D4002								
	Part #:156001-3S-0185								
	Possible Supplier: Aviall / API								
	Material release note required								
110	Receive & Inspect for Damage & Mat'l Certs	0.00							
110									
Packaging	Memo	0.01							
Packaging									

4 FEB 07 2017 4x 8017-0412

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
								Completed By	
								Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval					

Root Cause				FAULT CATEGORY			
Environment ☐	☐	No Re-verification	☐	Pressure/Forced	☐	Temperature/Cure	☐
Design ☐	☐	Operator	☐	Bending	☐	Set-up	☐
Doc/Data ☐	☐	Offset/Setup	☐	Centre Not Concentric	☐	BOM/Route	☐
Equip/Tooling ☐	☐	Supplier	☐	Cracks	☐	Broken/Damage/Defect	☐
Handling/Pre ☐	☐	Training	☐	Crimp/Kink/Ripple/Wave	☐	Inspection Incomplete/Unqualified	☐
Material ☐	☐	Use for Testing	☐	Cuffs	☐	Contamination	☐
Internal Transport ☐	☐	Poor Information	☐	Crushing	☐	Countersink	☐
Tribal Knowledge ☐	☐	Rushing	☐	Heat Treat	☐	Cut Too Short	☐
LOA ☐	☐	Product Improvement	☐	Wave/Twist in Tube	☐	Instructions Incomplete/Unclear	☐
Substation ☐	☐	Process Improvement	☐	Marks/Chatter	☐	Drill Holes	☐
Past Expiry Date ☐	☐	Manufacturing Process	☐	OTHER : _____			
Misidentified ☐	☐	Past Due	☐				

Friday, January 27, 2017 1:22:35 PM

Page 2

4 _____

DAS
38
9-00
FEB 17 2017

4 FF FEB 22 2017

4

DQA: _____ Date: _____

WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
							Completed By		
							Lead hand / Supervisor Approval Verification		
							QC / QA Coordinator Approval		

Root Cause				FAULT CATEGORY			
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐		
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐		
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐		
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐		
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐		
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐		
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐		
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐		
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐		
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐		
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____					
Misidentified ☐	Past Due ☐						

Work Order ID 156458

Friday, January 27, 2017 1:22:36 PM

156458

Page 3

Item ID: D4002-041

Accept

N900040100

Setup Start *NS1*

Revision ID:

Stop *NS2*

Item Name: Aux Tank Drain Hose Assy, Fwd

Start Date: 2/1/2017 Start Qty: 4.00 *4*

Cust Item ID:

Required Date: 2/9/2017 Req'd Qty: 4.00 *4*

Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start *NR1*

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop *NR2*

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

130 Identify as per dwg & Stock Location: Stall 0.00

130

Packaging

Memo

0.01

Packaging

4

DAS
6
9-89

FEB 23 2017

140 QC21- Final Inspection - Work Order Release 0.00

140

QC

Memo

0.07

Quality Control

17/2/23

DAS
21
9-89
FEB 23 2017

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
				Completed By					
				Lead hand / Supervisor Approval Verification					
				QC / QA Coordinator Approval					

Root Cause				FAULT CATEGORY			
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐		
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐		
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐		
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐		
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐		
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐		
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐		
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐		
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐		
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐		
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____					
Misidentified ☐	Past Due ☐						

Picklist Print

Friday, January 27, 2017 1:22:35 PM

Page 1
2

Work Order ID: 156458

156458

Parent Item: D4002-041

D4002-041

Parent Item Name: Aux Tank Drain Hose Assy, Fwd

Start Date: 2/1/2017

Required Date: 2/9/2017

Start Qty: 4.00

Required Qty: 4.00

Comments: IPP rev A 10.01.21 new issue Prelim EC verified by:DD IPP rev B
10.11.03 added MS29528-04 DD verified by:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
156001-3S-0185 *156001-3S-0185* Hose Assembly		Purchased	No			110	Each	0.0000	1	4			
AN894D4-3 *AN894D4-3* Fitting		Purchased	No			121	Each	8.0000	1	4			
Location ST323 m135979 m323 Loc Qty 8 2 6 Loc Code													
MS29512-04 *MS29512-04* O-Ring		Purchased	No			121	Each	61.0000	1	4			
Location ST274 m129682 Loc Qty 61 61 Loc Code													
MS29528-4 *MS29528-4* Fuel Drain Valve		Purchased	No			121	Each	5.0000	1	4			
Location GA m136090 Loc Qty 5 5 Loc Code													

4x SPI7-02-14

FEB 21 2017
DAS
6
9-89

2
136835

FEB 21 2017
DAS
6
9-89

4

FF FEB 22 2017

3
1

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
							Completed By		
							Lead hand / Supervisor Approval Verification		
							QC / QA Coordinator Approval		

Root Cause				FAULT CATEGORY			
Environment ☐	☐	No Re-verification	☐	Pressure/Forced	☐	Temperature/Cure	☐
Design ☐	☐	Operator	☐	Bending	☐	Set-up	☐
Doc/Data ☐	☐	Offset/Setup	☐	Centre Not Concentric	☐	BOM/Route	☐
Equip/Tooling ☐	☐	Supplier	☐	Cracks	☐	Broken/Damage/Defect	☐
Handling/Pre ☐	☐	Training	☐	Crimp/Kink/Ripple/Wave	☐	Inspection Incomplete/Unqualified	☐
Material ☐	☐	Use for Testing	☐	Cuffs	☐	Contamination	☐
Internal Transport ☐	☐	Poor Information	☐	Crushing	☐	Countersink	☐
Tribal Knowledge ☐	☐	Rushing	☐	Heat Treat	☐	Cut Too Short	☐
LOA ☐	☐	Product Improvement	☐	Wave/Twist in Tube	☐	Instructions Incomplete/Unclear	☐
Substation ☐	☐	Process Improvement	☐	Marks/Chatter	☐	Drill Holes	☐
Past Expiry Date ☐	☐	Manufacturing Process	☐	OTHER : _____			
Misidentified ☐	☐	Past Due	☐				

Picklist Print

Page 2

Friday, January 27, 2017 1:22:35 PM

Work Order ID: 156458

156458

Parent Item: D4002-041

D4002-041

Parent Item Name: Aux Tank Drain Hose Assy, Fwd

Start Date: 2/1/2017

Required Date: 2/9/2017

Start Qty: 4.00

Required Qty: 4.00

D2182-045

Manufactured No

121

Each

12.0000

1

4

D2182-045

Heat Shrink 4.5" Long

FEB 21 2017

DAS
6
9-88

Location

Loc Qty

Loc Code

ST003

12

141023

12

D2729-1

Manufactured Yes

121

Each

-16.0000

1

4

D2729-1

Part Id Label (Re-Issue)

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE


QA Closed: _____ Date: _____

Work Order update only ☐


Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
							Completed By		
							Lead hand / Supervisor Approval Verification		
							QC / QA Coordinator Approval		

Root Cause				FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabelled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐		
OTHER : _____							

ITEM NO.	QTY. -041	QTY. -043	PART NUMBER	DESCRIPTION	JOHN CAMERON AVIATION PART NUMBER
1	X		D4002-041	AUX TANK DRAIN HOSE ASSEMBLY, FWD	JCA-M47-1-13
2		X	D4002-043	AUX TANK DRAIN HOSE ASSEMBLY, AFT	JCA-M47-1-16
3	1		D4002-1	HOSE ASSEMBLY	
4		1	D4002-3	HOSE ASSEMBLY	
5	1	1	AN894D4-3	FITTING	
6	1	1	MS29512-04	O RING	
7	1	1	CCB4320	FUEL DRAIN VALVE (MS29528-4)	



D4002-041 DRAIN HOSE - FRONT



D4002-043 DRAIN HOSE - REAR

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 156458 MWS
17-02-02

RELEASED
2011-11-16
JWD


- NOTES:
- 1) MATERIAL: N/A
 - 2) FINISH: N/A
 - 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
 - 4) UNITS: INCHES UNLESS OTHERWISE NOTED
 - 5) BREAK SHARP EDGES: N/A
 - 6) IDENTIFICATION: IDENTIFY WITH DART P/N AND B/N USING D2729-1 LABEL INSTALLED WITH D2182-045 HEAT SHRINK
 - 7) WEIGHT: D4002-041 - 0.21 lbs
D4002-043 - 0.20 lbs
 - 8) DRAIN VALVE MAY NOT APPEAR EXACTLY AS PICTURED

REV.	DESCRIPTION	BY	DATE
D	ADDED NOTE 8	DC	11.10.06
C	ADDED 8.00" TO D4002-1/3 HOSES; AFFECTED WEIGHT	MB	11.09.14
B	CHANGE LENGTH MEASUREMENT FOR -3, ZN C2-2	HS	10.11.03
A	NEW ISSUE	HS	10.03.01
DESIGN			
DRAWN			
CHECKED			
MFG. APPR.			
APPROVED			
DE APPR.			
DATE	11.10.06		


DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWING NO. D4002	REV. D
TITLE HOSE ASSEMBLY	SCALE NTS
COPYRIGHT © 2010 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD	

DART AEROSPACE PART NUMBER	JOHN CAMERON AVIATION PART NUMBER
D4002-1	REF JCA-M47-1-13
D4002-3	REF JCA-M47-1-16
D4002-5	JCA-M47-2-13
D4002-7	JCA-M47-2-25


SPECIFICATION CONTROL DRAWING




D4002-1 HOSE ASSEMBLY



D4002-3 HOSE ASSEMBLY



D4002-5 SUPPLY HOSE - FROM AUX TANK



D4002-7 SUPPLY HOSE - PUMP TO MAIN TANK FILLER NECK

DART PART NUMBER	STRATOFLEX PART NUMBER	POSSIBLE VENDOR	LENGTH "L"	END FITTING "A"	END FITTING "B"	HOSE "C"	WEIGHT
D4002-1	156001-3S-0185	AVIALL/API	17.90	676-3S	676-3S	156-3	0.16 lbs
D4002-3	156001-3S-0154	AVIALL/API	14.76	676-3S	676-3S	156-3	0.15 lbs
D4002-5	156003-6D-0102	AVIALL/API	8.94	678-6D	676-6D	156-6	0.13 lbs
D4002-7	156005-6D-0213	AVIALL/API	20.31	680-6D	676-6D	156-6	0.19 lbs

RELEASED
2011-11-16

NOTES:

- 1) MATERIAL: N/A
- 2) FINISH: N/A
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) UNITS: INCHES UNLESS OTHERWISE NOTED
- 5) BREAK SHARP EDGES: N/A
- 6) IDENTIFICATION: IDENTIFY WITH DART P/N AND B/N USING D2729-1 LABEL INSTALLED WITH D2182-045 HEAT SHRINK
- 7) WEIGHT: SEE TABLE

DESIGN	<i>[Signature]</i>	DART AEROSPACE LTD	
DRAWN	<i>[Signature]</i>	HAWKESBURY, ONTARIO, CANADA	
CHECKED	<i>[Signature]</i>	DRAWING NO.	REV. D
MFG. APPR.	<i>[Signature]</i>	D4002	SHEET 2 OF 2
APPROVED	<i>[Signature]</i>	TITLE	SCALE
DE APPR.	<i>[Signature]</i>	HOSE ASSEMBLY	NTS
DATE	11.10.06	COPYRIGHT © 2010 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COMBINED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	



Dart Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
Tel: 613 632 9577
Fax: 613 632 1053

PURCHASE ORDER

Purchase Order ID **PO35229**

Purchase Order Date 2/7/2017

PO Print Date 2/8/2017

Page Number 1 of 5

Order From :

AVIALL
PO BOX 842275

DALLAS, TX 75284-2275
USA

VU-AVI003

Ship To : DART AEROSPACE LTD

1270 ABERDEEN
HAWKESBURY, ON K6A 1K7
CANADA

E-MAILED

REVISED QTY

Contact Name

Vendor Phone 905-676-1695

Ship To Contact

Ship To Phone

Ship Via: FedEx Overnight collect

Ship Acct:

Buyer

Chantal Lavoie

Customer POID

Customer Tax # 10127-2607

Terms

Net 30

Currency

USD

FOB

EXW - (Ex Works)

Line Nbr	Reference Vendor Part Number	Description/ Mfg ID	Req Date/ Taxable	CD	Req Qty/ Unit of Measure	PO Unit Price	Extended Price
	Line Comments		Promise Date				
	Delivery Comments						
1	156001-3S-0185	Hose Assembly	2/15/2017 Yes 2/15/2017		4.00 Each	\$449.23	\$1,796.92
	AS PER DWG D4002 REV. D B156458						
						Line Total:	\$1,796.92
2	156001-3S-0154	Hose Assembly	2/15/2017 Yes 2/15/2017		4.00 Each	\$106.85	\$427.40
	AS PER DWG D4002 REV. D B156518						
						Line Total:	\$427.40
3	600.1012	Sealant PR1425B2 (#654 sem)	2/15/2017 Yes 2/15/2017	FN	14.00 Each	\$59.03	\$826.42

PO Instructions: Fedex Acc#151793240

Note:

2/8/2017



PACKING LIST



DELIVERY NUMBER: 8004110341

ROUTE: US FedEx International Priority

PAGE:1 of 1
DATE:10FEB17
TIME:07:59:28
EMP:00000000
ORD TYP: ZOR 132
CURRENCY:USD
TERMS:Net 30

CUSTOMER PO:35229
ORDER NUMBER:1002839643
ORDER DATE:08FEB17

B 10003951
I DART AEROSPACE LTD
L 1270 ABERDEEN STREET
L HAWKESBURY ON K6A 1K7
T CANADA
O

S 10003951
H DART AEROSPACE LTD
I 1270 ABERDEEN STREET
P HAWKESBURY ON K6A 1K7
T CANADA
O

S 1009
H AVIALL DALLAS HOSE SHOP
I DALLAS HOSE SHOP
P 2755 REGENT BLVD
F DFW AIRPORT TX 75261
R USA
O

DAS
38
9-89

LINE	PO LINE	MFG	ITEM DESCRIPTION	ORDER QUANTITY	SHIP QUANTITY	QUANTITY BACK ORDER	UOM	CUSTOMER PRICE	EXTENDED CUSTOMER PRICE
00010	0	1S	156001-3S0185 HOSE: MED PRESSURE,RUBBER BATCH 100113310	4	4	0	EA	449.23	1,796.92
00020	0	1S	156001-3S0154 HOSE: MED PRESSURE,RUBBER BATCH 100113311	4	4	0	EA	106.85	427.40

8170214

This is not an Invoice.
For payment processing, please refer to Invoice.

The recipient of these goods agrees to comply with all export regulations governing the transfer, sale, lease, or use of these goods.
Diversion contrary to U.S. Law is prohibited.

CERTIFICATE OF CONFORMANCE

It is hereby certified that Aviall Services, Inc., is an approved distributor and meets all requirements of ISO9001, AS9100, AS9120 and AC 00-56 at 2750 Regent Blvd. DFW Airport, Texas. The products, articles or parts referenced on this document are in new or overhauled condition and were purchased from an approved source (FAA, EASA, TCCA, Mil Spec or Commercial). The Original Manufacturers' Certifications are maintained on file at our central office location, and copies are available upon request or at Aviall.com. For overhauled or repaired products, articles or parts, the original FAA 8130-3 / EASA Form 1 (Return to Service) or Yellow Tag, from the FAA/JAA/EASA approved Air Agency are attached to the component.

DISCOUNT TERMS APPLY ONLY TO SUB TOTAL. ALL
RETURNED MERCHANDISE SUBJECT TO HANDLING
FEE.
THIS IS TO CERTIFY THAT AVIALL HAS COMPLIED WITH
THE PROVISIONS OF THE FAIR LABOR ACT OF 1938
AMENDED.

CUSTOMER COPY



A BOEING COMPANY

AVIALL SERVICES INC
2750 REGENT BLVD
DFW AIRPORT TX 75261
USA

Commercial Invoice

Tracking Number	598520536768	Government Transaction Number	NOEEI FTR 30.36
Ship From	LU_US_1009	Delivery Number	8004110341
AVIALL DALLAS HOSE SHOP 2755 REGENT BLVD DFW AIRPORT TX 75261 USA		Commercial Invoice Number	9305103577
		Ship Date	10 February, 2017
		Incoterms	EXW Shipping Point

Sold To	10003951	Ultimate Consignee	10003951	Ship To	10003951	Freight Forwarder	400010
DART AEROSPACE LTD 1270 ABERDEEN STREET HAWKESBURY ON K6A 1K7 CANADA		DART AEROSPACE LTD 1270 ABERDEEN STREET HAWKESBURY ON K6A 1K7 CANADA		DART AEROSPACE LTD 1270 ABERDEEN STREET HAWKESBURY ON K6A 1K7 CANADA		FEDEX FEDEX NATIONAL LTL INC PO BOX 94515 PALATINE IL 60094-4515	
							Tax Number: 20-4734803

Comments:

Item	Part Number & Description	Country of Origin	Quantity	UOM	Unit Value USD	Extended Value USD
10	156001-3S0185 HOSE: MED PRESSURE,RUBBER Export Tariff: 4009220050 Export Classification: 9A991.d Authorization: NLRAT_FEB_2017 Sales Order: 1002839643 PO: 35229 Batch Number: 100113310	US	4	EA	449.23	1,796.92
20	156001-3S0154 - HOSE: MED PRESSURE,RUBBER Export Tariff: 4009220050 Export Classification: 9A991.d Authorization: NLRAT_FEB_2017 Sales Order: 1002839643 PO: 35229 Batch Number: 100113311	US	4	EA	106.85	427.40

SP17-02-14



A BOEING COMPANY

Commercial Invoice

Delivery Number	Commercial Invoice Number
8004110341	9305103577

Item	Part Number & Description	Country of Origin	Quantity	UOM	Unit Price USD	Extended Value USD
------	---------------------------	-------------------	----------	-----	-------------------	-----------------------

SA7-02-14

**FOR CUSTOMS PURPOSES ONLY
NOT A BILLING INVOICE**

Gross Value	2,224.32
Add on Charges	
Tax Value	
Freight Charges	
Total Net Value	2,224.32

These items are controlled by the U.S. Government and authorized for export only to the country of ultimate destination for use by the ultimate consignee or end user(s) here in identified. They may not be resold, transferred, or otherwise disposed of, to any other country or to any person other than the authorized ultimate consignee or end-user(s), either in their original form or after being incorporated into other items, without first obtaining approval from the U.S. government or as otherwise authorized by U.S. law and regulations.



Hose Shop 2755 Regent Blvd, Dfw Airport, TX 75261

Phone: 972-586-1380

Fax: 972-586-1381

WWW.AVIALL.COM

TSO CERTIFICATION

It is hereby certified that (A) The parts and/or materials reflected herein were produced under Federal Aviation Administration approved manufacturing and quality control system/methods as set forth in the FAA issued technical standard order authorizations (TSOA) issued to Stratoflex and (B) such parts and/or materials are new and are in condition for safe operation.


Aviall Order Number: 1002839643 ✓

0010: 156001-3S0185 ✓

4 ea.

0020: 156001-3S0154

4 ea.

Signed: 

Date: 02/09/2017

Aviall is not providing OEM parts. Aviall is an authorized Stratoflex distributor providing TSO assemblies. Numbers referenced per customer requirements are for customer reference ONLY and are in no way intended to be represented as OEM parts. Any reference to an OEM part number does not authorize or reflect installation authority for this part. The installation authority is provided by the mechanic installing this product in accordance with FAR Part 43. If applicable, satisfactory compliance with the conditions and tests required for TSO approval indicates the hose assembly has met the minimum performance standards as stated in the TSO. Furthermore, it is the responsibility of the installer to determine the installation eligibility and that it will not cause the hose assembly to be subjected to conditions in excess of those for which it has been